

Continuous Radon Monitor

Model Number: 1028
Calibration Date: 04/27/2007
Monitor Time: 10/17/2007 19:19

Serial Number: 49979024
CF: 2.98

Inspector Information

Eagle Home Inspection
3100 Shadyview Lane
Plymouth
Minnesota-55447
Phone Number: 763-442-4039

Customer Information

Pete Busch
3100 Shadyview Ln
Plymouth
Minnesota-55447
Phone: 763-442-4039


Site & Condition

Atmospheric Condition: NA

Test Summary

Start Time: 10/10/2007 21:24
End Time: 10/12/2007 21:24
Measurement Interval(hr): 1.0
Elapse Time: 2 Days 0 hrs

Overall Avg: 2.3 pCi/l
EPA Avg: 2.4 pCi/l



***** 10/10/2007 *****

Time	Counts pCi/l	Flags
22:24	1.3	
23:24	1.7	

***** 10/11/2007 *****

Time	Counts pCi/l	Flags
00:24	5.4	
01:24	2.7	
02:24	2.7	
03:24	3.7	
04:24	1.0	
05:24	4.0	
06:24	0.3	
07:24	1.3	
08:24	1.7	
09:24	1.7	
10:24	2.3	
11:24	1.3	
12:24	2.7	
13:24	1.7	
14:24	4.0	
15:24	1.0	
16:24	2.3	
17:24	1.7	
18:24	2.3	
19:24	2.7	
20:24	4.0	
21:24	3.7	
22:24	1.7	
23:24	2.7	

***** 10/12/2007 *****

Time	Counts pCi/l	Flags
00:24	1.3	
01:24	2.0	
02:24	2.3	
03:24	3.0	
04:24	2.0	
05:24	1.7	
06:24	2.7	
07:24	1.3	
08:24	4.7	
09:24	2.0	
10:24	1.7	
11:24	2.3	

***** 10/12/2007 *****

Time	Counts pCi/l	Flags
12:24	2.3	
13:24	1.7	
14:24	3.4	
15:24	1.3	
16:24	3.7	
17:24	2.7	
18:24	2.7	
19:24	0.7	
20:24	2.0	
21:24	3.0	

Error Flags:

M Motion:

Inspector Signature _____

PC Software Version: 2.0.0.0

Embedded Software Version: 104